

# Light Pole Instructions - Above Wall Height Bar


- PARTS LIST:
- (1) Male No-Color Pole section – 61"
  - (1) Female No-Color Pole section – 58 ¼"
  - (2) Short riser pole sections – snap buttons both ends
  - (2) Stabar EII Joints
  - (2) Indoor EII Joints



Stabar EII



Indoor EII




Female

Male

## ASSEMBLY:

1. While assembling the roof frame (for a canopy) or the upper horizontal poles (for an indoor booth), slide the Stabar EII joints onto the upper horizontal poles opposite each other (see diagram below).



**Note:** Canopy rafter poles and hardware not seen in this view. For ProMaster booth frame, no front bar will be included (see canopy or ProMaster setup instructions).

2. Assemble no-color pole using male and female sections.
3. Attach an EII Joint to each end of the no color pole.
4. Insert riser pole into each of the Tee Joints and click in place.
5. Slide EII Joint onto riser poles one at a time and click into place
6. Tighten all thumbscrews for added stability.
7. Clamp or track lighting may then be attached to the light pole.